

## DEPARTMENT OF CIVIL ENGINEERING GOVT, ENGINEERING COLLEGE, THRISSUR - 9

## Ph: 0487-2322989

09.02.2023

STRUCTURAL STABILITY REPORT OF EXISTING BUILDING AT SOUTH CHITTOOR (S.B.O.A PUBLIC (Sr. Sec.) SCHOOL, SOUTH CHITTOOR, CHERANELLOOR VILLAGE, CHERANELLOOR PANCHAYATH, EDAPPALLY BLOCK, WARD NO. X, SURVEY NO. 289/1, 290/1, 290/2, 290/3, BUILDING NO. X/406A, ERNAKULAM DISTRICT)

As Per the request letter from The Principal, SBOA Public Sr. Sec. School, South Chittoor, I have visited the building site. I have inspected Two buildings. Both are of (G+3) Floors. It is found that the structural members such as columns are found intact. Non-structural cracks were also not observed on the walls. No cracks were seen on these structural members. Upon Non-destructive (Rebound hammer) testing, the structural concrete is "having designed strength. From the inspection & NDT testing, the building is found to be safe under Normal Weather Conditions.

However the following points are noted in connection with the above.

1. Need of safety certificate from fire department is not checked.

NUSUR-160 DCD

- The other construction quality aspects, especially construction joints, construction of walls etc. are not checked in this investigation
- In future, any new crack found in the structure, the same should be consulted to a structural engineer and the necessary measures should be taken.
- 4. The Confirmation for KMBR/KPBR of the Building has not been verified

Assis

Assistant Professor in Civil Engineering

DE STANT WE STUDY SOM

y SyDonespondou Educational Trust

SREEKALA KARUNAKARAN PRINCIPAL SBOA PUBLIC (SR. SEC.) SCHOOL SOUTH CHITTOOR, KOCHI-682 027

